Scope of	Work for Property Loc	ated at:		<u>5036</u>	North 38th	n Street	
	Property is: Single Fan	nily 🗹	Duplex		Other $\square$		_
Date:	11/5/2014						
take no respo		after the ins	pection dat	e, or for	omissions throu	, the Redevelopment Authority, and their re gh error or oversight. The list does not ned E programs.	
Exterior (	Condition Report						
Location Site	Required Work Landscaping	n/a 🔽	Yes 🗌	Note/ Self He	Comments elp	\$	Cost
	Steps/Handrails	n/a ✓	Yes 🗌			\$	
	Service walks	n/a ✓	Yes 🗌			\$	
	Fencing	n/a 🗌	Yes 🗸			\$	350.00
	Parking	n/a ✓	Yes 🗌				
	Retaining walls	n/a ☑	Yes 🗌			\$	
	Other	n/a 🔲	Yes 🗌			\$	
	Other	n/a 🗌	Yes 🗌			\$	
Garage	Singles: repair	n/a 🗸	Yes 🗌			\$	
	Shingles: Roof over existing	n/a 🗸	Yes 🗌			\$	
	Shingles:Tear off & re-roof	n/a ✓	Yes 🗌			\$	
	Gutters/downspouts	n/a 🗸	Yes 🗌			\$	
	Flashing	n/a 🗸	Yes 🗌			\$	
	Eaves	n/a 🗌	Yes ✓			\$	350.00
	Siding	n/a 🔲	Yes ✓			\$	3,000.00
	Doors	n/a 🔲	Yes ✓			\$	400.00
	Windows	n/a 🗸	Yes 🗌			\$	
	Slab	n/a ✓	Yes 🗌			\$	
	Paint	n/a 🗌	Yes ✓			\$	450.00
	Electrical	n/a 🗸	Yes 🗌			\$	
Davahaa	Other	n/a 🗌	Yes 🗌			\$	
Porches	Roof	n/a 🗌	Yes 🗸			\$	2,200.00
	Deck-upper	n/a 🔲	Yes 🗸			\$	2,500.00
	Decklower	n/a 🗌	Yes 🗸			\$	6,500.00
	Steps/handrails	n/a 🔲	Yes ✓			\$	1,800.00
	Ceiling	n/a ✓	Yes 🗌			\$	
	Guardrails	n/a 🔲	Yes ✓			\$	1,800.00
	Structural	n/a ✓	Yes 🗌			\$	
	Paint	n/a 🗌	Yes 🗸			\$	950.00

n/a Yes 🗌

\$

Other

## House

Chimney	n/a Yes 🗸 tuc	ckpoint \$	300.00
Shingles: repair	n/a 🗸 Yes 🗌	\$	
Shingles: Roof over existing	n/a 🗹 Yes 🗌	\$	
Shingles:Tear off & re-roof	n/a Yes 🗸	\$	8,800.00
Gutters/downspouts	n/a Yes 🗸	\$	850.00
Flashing	n/a 🗸 Yes 🗌	\$	
Eaves	n/a 🗸 Yes 🗌	\$	
Siding	n/a Yes 🗸	\$	2,500.00
Storm Doors	n/a 🗸 Yes 🗌	\$	
Prime ("main") Doors	n/a Yes 🗸	\$	1,350.00
Storm Windows	n/a 🗸 Yes 🗌	\$	
Prime ("main") Windows	n/a Yes 🗸	\$	2,200.00
Paint	n/a 🗸 Yes 🗌	\$	
Foundation	n/a 🗸 Yes 🗌	\$	
Electrical	n/a 🗸 Yes 🗌	\$	
Other	n/a Yes	\$	
Other	n/a 🗌 Yes 🗌	\$	
Other	n/a Yes	\$	
Other	n/a Yes	\$	

Exterior: Estimated Cost:\* \$ 36,300.00
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report							
	Unit: Entire unit (single family)	~				Lower unit of duplex		
Mechanical	Upper unit of duplex Required Work	Ш				Other		
Heating	- 4-							
	Repair/replace boiler	n/a	<b>√</b>	Yes		_		\$ 
	Repair radiation	n/a	<b>✓</b>	Yes				\$
	Repair/replace furnace	n/a		Yes	<b>V</b>	_		\$ 3,000.00
	Repair ductwork	n/a	<b>V</b>	Yes		_		\$
	Replace thermostat	n/a		Yes	<b>V</b>	_		\$ 100.00
	Repair/replace grilles	n/a	<b>7</b>	Yes		_		\$
Floatsiaal	Tune boiler/furn. insp ht exchange	n/a	<b>V</b>	Yes		_		\$
Electrical	Repair/replace receptacles	n/a		Yes	7			\$ 1,000.00
	Repair/replace switches	n/a		Yes	7	_		\$ 500.00
	Repair/replace fixtures	n/a		Yes	7	_		\$ 1,500.00
	Install outlets and circuits	n/a	<b>4</b>	Yes		_		\$
	Install outlets and circuits	n/a	<b>V</b>	Yes		_		\$ 
	Install outlets and circuits	n/a	<b>V</b>	Yes				\$
	Install outlets and circuits	n/a	<b>V</b>	Yes		_		\$
	Upgrade service	n/a		Yes	<b>V</b>	_		\$ 1,800.00
	Other	n/a		Yes				\$
	Other	n/a		Yes				\$
Plumbing	Repair/replace kitchen sink	n/a		Yes	7			\$ 1,500.00
	Repair/replace kitchen sink fauce	n/a		Yes	7	_		\$ 450.00
	Repair/replace tub	n/a		Yes	7			\$ 900.00
	Repair/replace tub faucet	n/a		Yes	<b>V</b>			\$ 450.00
	Repair/replace toilet	n/a		Yes	<b>V</b>			\$ 300.00
	Repair/replace lavatory	n/a		Yes	<b>V</b>			\$ 350.00
	Repair/replace lavatory faucet	n/a		Yes	7			\$ 300.00
	Repair/replace wash tub	n/a		Yes	<b>4</b>			\$ 750.00
	Repair/replace wash tub faucet	n/a		Yes	<b>4</b>			\$ 350.00
	Unclog piping:	n/a		Yes	<b>y</b>	back up & flooding	9	\$ 1,200.00
	Repair drain/waste/vent piping	n/a		Yes	<b>V</b>			\$ 2,500.00
	Repair water piping	n/a		Yes	1			\$ 3,000.00
	Repair/replace water heater	n/a		Yes	<b>y</b>			\$ 850.00
	Other	n/a		Yes	<b>4</b>	remove 2nd fl kitcl	hen sink & bath or make legal	\$ 1,500.00

Other n/a Yes S

Windows							
	Replace broken glass	n/a <u></u> ✓	Yes	<u> </u>	_	\$	
	Repair or replace sash	n/a 🔽	Yes	<b> </b>	_	\$	
Doors	Repair or replace doors	n/a 🗀	Yes	s 🗸		\$	600.00
	Repair or repl. locks/latches	n/a _	Yes	<b>V</b>	Self Help	\$	180.00
Walls/Ceiling	Repair or repl. @ defective	n/a	Yes	\$ <b>/</b>		\$	6,500.00
Paint	Repair or repl. @ defective	n/a _□	Yes	<b>.</b>	_	\$	2,500.00
Fire Safety							
	Install smoke/CO alarm:bsmt.	n/a	Yes	S 🗸	Self Help	\$	40.00
	Install smoke/CO alarm: 1st flr.	n/a 🗌	Yes	· 🗸	Self Help	\$	40.00
	Install smoke/CO alarm: 2nd flr.	n/a 🗀	Yes	<b>V</b>	Self Help	\$	40.00
Handrails	Repair/replace defective	n/a _	Yes	\$ <b>7</b>	Self Help	\$	250.00
Stairs	Repair defective	n/a _	Yes	\$ <b>7</b>		\$	750.00
Floors	Repair defective	n/a 🗀	Yes	s 🗸		\$	3,200.00
Other		n/a 🗀	Yes	s 🗸	illegal 2nd floor unit - discontinue use	\$	2,000.00
		n/a _	Yes	; <u> </u>		\$	
		n/a	Yes	<b></b>		\$	
		n/a _	Yes	<u> </u>	_	\$	
					Interior: Estimated Cost:	\$	38,400.00
					Total Exterior and Interior Cost:*	\$	74,700.00
		*average contracted cost Actual costs may vary. Self help will reduc	e the amount				

Inspected by: Mark Pelzek Date: 11/5/14

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount